

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)	Examiner: Jennifer T. Nguyen Group Art Unit: 2674
SHINJI SHIRAGA	:)	
Appl. No.: 08/794,772	;)	
Filed: February 3, 1997)	
For: BATTERY POWERED ELECTRICAL EQUIPMENT WITH POWER SAVING OPERATION	; ; ;	
U.S. Patent No.: 6,947,035 B1	;)	
Issued: September 20, 2005)	Date: August 30, 2006
Commissioner for Patents Attn.: Certificate of Corrections Branch		

CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

 $_{ ext{Of}}$ Correction

Sir:

P.O. Box 1450

Alexandria, VA 22313-1450

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

08/31/2006 SDENBOB1 00030148 6947035 01 FC:1811 108.00 OP

> 6.1. 3 9 200 20 Cadad

Patentee's undersigned attorney may be reached in our Costa Mesa,
California office by telephone at (714) 540-8700. All correspondence should continue to
be directed to our address given below.

Respectfully submitted,

Edward A. Kmett Attorney for Patentee Registration No.: 42,746

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 Facsimile: (212) 218-2200

CA_MAIN 115855v1

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

6,947,035 B1

DATED

September 20, 2005

INVENTOR(S) :

SHINJI SHIRAGA

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

(30) FOREIGN APPLICATION PRIORITY DATA:

"5/218828" should read --5-218828--.

COLUMN 1:

Line 44, "desirable, power" should read --desirable power--.

COLUMN 4:

Line 15, "2 W 2" should read --2 W (2--.

Line 16, "watts) the" should read --watts). If the--.

Line 29, "mode 1 to 6" should read --modes 1 to 6--.

Line 57, "of" should be deleted.

COLUMN 5:

Line 51, "1106." should read --battery 1106.--

Line 67, "easily" should read --can easily--.

COLUMN 6:

Line 2, "changing" should read --direct changing--. Line 34, "mode 1-6." should read--modes 1-6.--


MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30)

PATENT NO. <u>6,947,035 B1</u>

No. of add'l. copies @ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

6,947,035 B1

DATED

September 20, 2005

INVENTOR(S) :

SHINJI SHIRAGA

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 7:

Line 22, "2 w" should read --2 W--. Line 31, "less" should read --lower--.

COLUMN 8:

Line 59, "above" should read --above,--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30)

PATENT NO. <u>6,947,035 B1</u>

No. of add'l. copies @ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

6,947,035 B1

DATED

September 20, 2005

INVENTOR(S) :

SHINJI SHIRAGA

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

(30) FOREIGN APPLICATION PRIORITY DATA:

"5/218828" should read --5-218828--.

COLUMN 1:

Line 44, "desirable, power" should read --desirable power--.

COLUMN 4:

Line 15, "2 W 2" should read --2 W (2--.

Line 16, "watts) the" should read --watts). If the--.

Line 29, "mode 1 to 6" should read --modes 1 to 6--.

Line 57, "of" should be deleted.

COLUMN 5:

Line 51, "1106." should read --battery 1106.--

Line 67, "easily" should read --can easily--.

COLUMN 6:

Line 2, "changing" should read --direct changing--.

Line 34, "mode 1-6." should read--modes 1-6.--

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30)

PATENT NO. <u>6,947,035 B1</u>

No. of add'l. copies @ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

6,947,035 B1

DATED

September 20, 2005

INVENTOR(S) :

SHINJI SHIRAGA

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 7:

Line 22, "2 w" should read --2 W--. Line 31, "less" should read --lower--.


COLUMN 8:

Line 59, "above" should read --above,--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile PATENT NO. <u>6,947,035 B1</u>

No. of add'l. copies @ 30¢ per page



Form PTO 1050 (Rev. 3-82) (Form#30)